

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name Hay Al Iskan Basic mixed - Jerash
Package Package 2
Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Rep No. QC-21 09
Date 3 / 06 / 2021

Description of Non Conformance	Corrective Action	Required by / When
Narrow spaces in block walls must not be filled with mortar	Saw cut blocks must be used.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor has taken immediate action.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Before

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



After

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature