

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 06**
Date **21 / 04 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Location: Wall at axis (J-K)/17 and columns J/17. - Concrete Segregation. - Exposed Steel Reinforcement.	To be repaired by approved repair material and take measures to avoid this non-conformance in future concrete casting.	Immediately by Contractor.
<p align="center">Report Prepared by</p>	Hassan Shaqbua, Supervision Quality Control Manager	

Contractor's Response
The Contractor started with the remedy of defected area on 24/04/2021.
<p align="center">Notes</p>

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature