Quality Control Report



2021

Consultant	Wahib Medanat Consultant Engineers	Rep No.	QC-12 03
Site Name	Al Khansa'a Basic Mixed - Balqa	Date	18 / 04 / 2
Package	Package 1		
Contractor	Derar Saraireh & Sons for Engineering & Contracting		
Tender No.	1/2020/USAID/SKEP/3/1		

Description of Non- Conformance	Corrective Action	Required by / When
Hair cracks in the slab on grade and the slab of the sewage collection tank.	Repair using approved repair material and avoid cracks in the future casting by more attention to be taken for curing using burlap in hot weather.	Immediately by Contractor.
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	

Contractor's Response

The Contractor has not started yet with the remedy work. He provided burlap for next concrete casting.

Notes

Consultant Site Engineer


Contractor Site Engineer

Signature

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Consultant Site Engineer


Contractor Site Engineer

Signature

Signature

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Schools for Knowledge Economy Project SKEP III

Quality Control Report





Consultant Site Engineer

Contractor Site Engineer