

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name Hay Al Iskan Basic mixed - Jerash
Package Package 2
Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Rep No. QC-21 08
Date 31 / 05 / 2021

Description of Non Conformance	Corrective Action	Required by / When
Segregation in boundray wall appeared on 31/05/2021	Chipping, clearing and repair using approved material	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor responded on 01/06/2021 and repaired under the supervision of consultant staff		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



1- Defected Action

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



2- Corrective Action

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature