

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 10**
Date **12 / 10 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Built stones at entrance not complying with sample and poor workmanship.	Remove built area- and re-build in compliance with specifications.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor responded immediately.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected stone building

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Removal of defected built stone

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

3/4

10/31/2021

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2301-2303\
QC-231012102021.xlsx

Quality Control Report



Re-building the stone correctly

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature