

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 05**
Date **8 / 04 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Location: Wall neck at axis (11-17)/(H-I) - Concrete Segregation - Concrete Roughness - Exposed Steel Reinforcement.	To be repaired by approved repair material and take measures to avoid this non-conformance in future concrete casting.	Immediately by Contractor.

Report Prepared by

Hassan Shaqbua, Supervision
 Quality Control Manager

Contractor's Response

The Contractor has completed all remedy works on 20/04/2021

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature