

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 11**
Date **6 / 12 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
1. Defects in porcelain floor tiles. 2. Defects in granite of staircases.	1. Replace the defected tiles. 2. Replace the defected granite tiles.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
It was observed that the Contractor started with replacing the defected porcelain floor tiles.		
Notes		

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Before Photos:



Defected porcelain floor tiles



Defected granite tiling

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Starting with the removal of defected porcelain floor tiles

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature