

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** Hay Al Iskan Basic mixed - Jerash  
**Package** Package 2  
**Contractor** Dijlah Est. Construction Co.  
**Tender No.** 10/2019/USAID/SKEP/3/2

**Rep No.** QC-21 06  
**Date** 1 / 04 / 2021

Description of Non Conformance	Corrective Action	Required by / When
1- Cracks in the ground slab. 2- Roughness, segregation and similar defects as per photos.	Using the approved material to conduct repair works with close follow up by the supervision engineer	Contractor to take action without delay.
<p align="center"><b>Report Prepared by</b></p>	Hassan Shaqbua, Supervision Quality Control Manager	
<p align="center"><b>Contractor's Response</b></p>		
No action by Contractor to date.		
<p align="center"><b>Notes</b></p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature