

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 06**
Date **17 / 07 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
<p>1. Radiators: First fix has been executed top-bottom without approval. 2. Stone Building: Chisseling pattern not unified as per approved sample. The built stone has mortar on the face due to the backing concrete.</p>	<p>1. Should be done as per final approval by the Engineer. 2. Replacement of stones not complying with the sample.</p>	<p>The Contractor/Immediately</p>
<p>Report Prepared by</p>	<p>Hassan Shaqbua, Supervision Quality Control Manager</p>	
<p>Contractor's Response</p>		
<p>Contractor responded immediately. The Contractor submitted method statement for chipping for MEP first fix and prepared a sample for fixing radiators.</p>		
<p>Notes</p>		

Consultant Site Engineer
Signature


Contractor Site Engineer
Signature

Quality Control Report

Before Photos:



Radiators first fix have been installed top- bottom without approval



Number of stones are broken, the gaps should be unified and the part of façade needs to be cleaned

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Replacing stones



Replacing stones

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature