## **Quality Control Report**



Consultant Site Name Package Contractor Tender No.	Wahib Medanat Consultant Engineers Khadija Bint Khwailed Basic Mixed - Balqa Package 1 Derar Saraireh & Sons for Engineering & Contracting 1/2020/USAID/SKEP/3/1		Rep No. Date	QC-13 12 20 / 12 / 2021
Description of Non Conformance		Corrective Action	Required by / When	
	floor tiling. stones/broken stones due to pointing	<ol> <li>Removal/Replacing the defects.</li> <li>Rectify/Replace the defects.</li> </ol>	The Contr	ractor/Immediately
Repo	rt Prepared by	Hassan Shaqbua, Supervision Quality Control Manager		
Contra	ctor's Response			
remarks: 1. Starting w defected floo	ectified previous rith removal of or tiles. g steel door frames			
Notes				

**Consultant Site Engineer** 

Contractor Site Engineer

### Schools for Knowledge Economy Project SKEP III

## Quality Control Report



### **Before Photos:**



Defected stone works

Consultant Site Engineer

**Contractor Site Engineer** 

### Schools for Knowledge Economy Project SKEP III

# Quality Control Report





**Defected Porcelain floor tiles** 



Unwrapped steel door frame

**Consultant Site Engineer** 

**Contractor Site Engineer** 

Signature

### Quality Control Report Photos After:





Starting with the removal of defected porcelain floor tiles



Wrapped steel door frame

**Consultant Site Engineer** 

**Contractor Site Engineer** 

Signature