

# Quality Control Report



**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Jumana Bint Abi Taleb Basic Mixed - Marka**  
**Package** **Package 2**  
**Contractor** **Dijlah Est. Construction Co.**  
**Tender No.** **10/2019/USAID/SKEP/3/2**

**Rep No.** **QC-23 04**  
**Date** **6 / 06 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Poor workmanship in blockwork in some parts of internal partion.	Remove defected parts and re-build properly.	Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>		
Immediate action by Contractor		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Before**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**After**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Before**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**After-1**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**After-2**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature