

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 08**
Date **17 / 10 / 2021**

Description of Non-Conformance	Corrective Action	Required by / When
1. Door frames: Dimensions do not comply with the drawings and specifications. 2. Electrical pipes are open (first fix).	1. Remove and provide frames with the right dimensions. 2. Close the pipes temporarily to avoid entering impurities.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	The Contractor responded to points 1 and 2.	
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Starting to remove the defected door frame

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Open electrical pipes

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Protected electrical pipes

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature