

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 11**
Date **16 / 10 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Tiled area problems in verticality and horizontality.	Remove and re-tile.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor responded immediately.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected tiling at toilet

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Removal of defected tiles

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Re-tiling at the toilet

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature