

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 08**
Date **21 / 09 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
1. Door frames of the sanitary units at the recess nit supported.	1. To be supported by mass concrete with appropriate dimension.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor has not responded yet		
Notes		

Consultant Site Engineer
Signature

Contractor Site Engineer
Signature

Quality Control Report

Before Photos:



Door frame supported by blocks

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

2/3

10/3/2021

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\Pk2- Yanal 30-9\
QC- 220821092021.xlsx

Quality Control Report

Photos After:

Consultant Site Engineer
Signature

Contractor Site Engineer

Signature

3/3

10/3/2021