

Quality Control Report



Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 05**
Date **27 / 06 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Major defects in the plastering have been observed in the mock up-room.	Due to major defects in the plastering, removal of plastering is required.	The Contractor/ Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor is still not taking action.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature