

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 13**
Date **27 / 10 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Defects in horizontality and verticality of the wall tiles at a number of locations in the toilets.	The Contractor was requested to remove the defected areas and re-tile correctly.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor still not responding.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos



Defected tiling at toilets (1)

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

2/4

10/31/2021

C:\Users\o.naddaf\Desktop\QCs-Ncs Sequence\2101-2106\
QC- 211327102021.xlsx

Quality Control Report



Defected tiling at toilets (2)

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Photos After:

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature