

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Um Al Dananir Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-11 20**  
**Date** **7 / 06 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Defects in installation of aluminum curtain wall. 2. Small cut-off pieces at the staircase parapet. 3. Damaged cabinet for the patch panel (Data System).	1. Relocate. 2. Replace with one piece. 3. Repair.	The Contractor/Immediately
<b>Report Prepared by</b>	Hassan Shaqbu, Supervision Quality Control Manager	
<b>Contractor's Response</b>	The Contractor responded to remark no. (2) and (3)	
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Wrong installation of curtain wall**



**Small cut-off pieces of granite**

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



**Damage in patch panel cabinet**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report

## Photos After:



**Replacement of small pieces**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Repair of patch panel cabinet**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature