

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Khadija Bint Khwailed Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-13 19**
Date **27 / 07 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
<ol style="list-style-type: none"> 1. Incorrect installation of the gypsum board. 2. Damaged base plate and damaged wall around the wall fans. 	<ol style="list-style-type: none"> 1. Rectify. 2. Repair. 	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
<ol style="list-style-type: none"> 1. The Contractor rectified the waving in plastering and painting of walls in the corridors. 2. Replacing the granite at staircase due to the black spots. 		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Incorrect installation of the gypsum board

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Damaged base plate and damaged wall around the wall fans

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Rectifying the waving in plastering and painting of walls at the corridors

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Replacing the granite at staircase due to the black spots

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

5/5

8/3/2022

C:\Users\o.naddaf\Desktop\Qcs-July 2022\
QC-131927072022.xlsx