

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Hay Al Iskan Basic mixed - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-21 01**
Date **11 / 01 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Concrete segregation in boundary walls and footings. The Contractor applied bitumen insulation material before treating the defected areas.	Removing the applied bitumen over the defected areas, then remedy the defected areas with the repair material	Contractor is requested to take action immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
Immediate action was taken by Contractor (photos attached)		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature