

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Al Khansa'a Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-12 02**
Date **8 / 02 / 2021**

Description of Non-Conformance	Corrective Action	Required by / When
Minor and limited segregation in the boundary wall as shown in the attached photo.	Repair using approved materials	Contractor, immediately.

Report Prepared by

Hassan Shaqbua, Supervision
 Quality Control Manager

Contractor's Response

The Contractor responded positively and promptly and repaired as required.

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature