

Consultant Wahib Medanat Consultant Engineers Rep No. QC-22 14

Site Name Thahr Al Sarow Basic Boys - Jerash Date 6 / 03 / 2022

Package Package 2

Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Description of Non Conformance	Corrective Action	Required by / When
1. Corrosion was observed in steel protection screens.	1. Rectify.	The Contractor/Immediately
2. Broken staircase tread.	2. Replace.	
3. Gaps between fire hose	3. Rectify.	
cabinets and walls and variations	1	
in levelling.	1	
4. Minor teething in porcelain	4. Rectify/Replace.	
floor tiles.	1	
5. Defects in granite cladding for	5. Rectify/Replace.	
staircase still existing.		
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	•

Contractor's Response

domination a reaponat	
The Contractor responded and rectified remarks no. 1 and 4.	
Notes	

4/3/2022

Before Photos:





Corrosion in steel protection screens



Broken staircase tread





Defects in installing of fire hose cabinet



Teething in porcelain floor tiles

4/3/2022






Defects in granite cladding for staircase

Photos After:





Rectified steel protection screens


4/3/2022





Replacement of defected tiles





Replacement of defected tiles

QC-221406032022.xlsx