

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Khadija Bint Khwailed Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-13 04**  
**Date** **8 / 03 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
<p>Minor segregation appeared in western retaining wall after removing formwork.</p>	<p>Repair is required using the approved materials.</p>	<p>The contractor was requested to take action immediately.</p>
<p><b>Report Prepared by</b></p>	<p>Hassan Shaqbua, Supervision Quality Control Manager</p>	
<p><b>Contractor's Response</b></p>		
<p>The Contractor responded promptly. Photos attached.</p>		
<p><b>Notes</b></p>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Segregation in Retaining Wall- QC Report 1304



Repair of Segregation- QC Report 1304

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature