

Quality Control Report


Consultant **Wahib Medanat** Consultant Engineers
Site Name **Thahr Al Sarow Basic Boys - Jerash**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-22 01**
Date **10 / 01 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Vertical Excavation	Boundary Walls	Construction Contractor/ Urgent
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response	Construction Contractor responded immediately	
Notes	Recommendation by the approved laboratory to construct the walls without delay, otherwise to construct shoring system.	

Consultant Site Engineer

Signature



Contractor Site Engineer

Signature


Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature



Signature