Schools for Knowledge Economy Project SKEP III

Quality Control Report





Rep No.	QC-13	13	
Date	12	/ 01 /	2022

Description of Non Conformance	Corrective Action	Required by / When
1. Defects in the installed coping at the roof parapet.	1. To be replaced	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	•
Contractor's Response		
The Contractor responded immediately.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Quality Control Report



Before Photos:



Defected stone coping

Consultant Site Engineer

Contractor Site Engineer

Schools for Knowledge Economy Project SKEP III

Quality Control Report Photos After:





Removal of defected stone coping

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature