

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** Hay Al Iskan Basic mixed - Jerash  
**Package** Package 2  
**Contractor** Dijlah Est. Construction Co.  
**Tender No.** 10/2019/USAID/SKEP/3/2

**Rep No.** QC-21 05  
**Date** 11 / 03 / 2021

Description of Non Conformance	Corrective Action	Required by / When
Segregation was observed after the removal of the formwork for the boundary wall (BW1 - Part 5).	The segregated areas need to be repaired using the approved repair material.	The remedy work is required by the Contractor immediately.
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Contractor's Response</b>		
The contractor does not take action to this date. He is expected to do the repairs within two days.		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Photo No. 1



Photo No. 2

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature