

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Um Al Dananir Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-11 21**  
**Date** **16 / 07 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Broken edges of the window sills.	1. Rectify.	The Contractor/Immediately
<b>Report Prepared by</b>		
<b>Contractor's Response</b>		
1. Replacing the small pieces of granite parapet cover of the staircase by larger suitable pieces. 2. Rectifying the fixation of aluminum Curtain wall. 3. Replacing the unacceptable red grout for granite coping with the approved grout. 4. Re-installing of Data System cabinet without causing damages.	Hassan Shaqbua, Supervision Quality Control Manager	
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report

## Before Photos:



**Broken edges of the window sills**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report

## Photos After:



**Replacing the small pieces of granite parapet cover of the staircase by larger suitable pieces**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Rectifying the fixation of aluminum Curtain wall**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature



# Quality Control Report



**Replacing the unacceptable red grout for granite coping with the approved grout**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



**Re-installing of Data System cabinet without causing damages**

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature