

Consultant Wahib Medanat Consultant Engineers Rep No. QC-22 13

Site Name Thahr Al Sarow Basic Boys - Jerash Date 22 / 02 / 2022

Package Package 2

Contractor Dijlah Est. Construction Co.
Tender No. 10/2019/USAID/SKEP/3/2

Description of Non Conformance	Corrective Action	Required by / When
 Defects in the built stones. Defects in granite cladding for the staircase are still exiting. 	 Replace defected stones. Replace. 	The Contractor/Immediately
3. Teething in granite tiling of landing.	3. Rectify.	
4. Defects in wall ceramic cutting adjoining the door frames.	4. Replace.	
5. Teething and defects in grouting for ceramic wall tiles.	5. Replace/Rectify.	
6. Teething in porcelian floor tiles.	6. Rectify.	
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	'

Contractor's Response

The Contractor responded to point 6 only.	
Notes	

Before Photos:





Defects in the built stones



Defects in the built stones





Teething in the granite cladding for staircases



Teething in the granite tiles for landing





Defects in ceramic cutting adjoining the door frame



Teething and defects in grounting of the wall ceramic





Teething in the floor porcelain tiles

Photos After:





Removing of defected porcelain tiles