

Consultant Wahib Medanat Consultant Engineers Rep No. QC-12 11

Al Khansa'a Basic Mixed - Balga Site Name **Date** 12 / 01 / 2022

Package Package 1

Contractor **Derar Saraireh & Sons for Engineering & Contracting**

Tender No. 1/2020/USAID/SKEP/3/1

Corrective Action	Required by	/ When
CONTECTIVE ACTION	Kequiled by	AAIIEII

The Contractor/Immediately

1. Damaged cartonal boards and 1. To be replaced with new asphalt paint for the external

Description of Non-

Conformance

2. Wall tiles: Cut-off pieces at the sides are less than the minimum required.

concrete footing members.

- 3. Broken window sills and length is less than required.
- boards after re-painting by asphalt.
- 2. To be removed and re-tiled as per requirement.
- 3. To be replaced.

Hassan Shaqbua, Supervision Quality Control Manager

Report Prepared by

Contractor's Response

The Contractor rectified the defects in stone around the rain water outlets and created the required grooves in the treads of the staircase at the factory.

Notes

2/1/2022

Before Photos:





Damaged cartonal

QC-121112012022.xlsx

2/7





Small cut-off pieces of tiles

QC-121112012022.xlsx

Signature






Broken sill and shortage in length

4/7





Broken stone around the outlet pipe



Stairs treads without grooves

Photos After:





Finishing around the outlet pipes

6/7





Stairs treads with grooves

<mark>7</mark>/7