

Site Visit Report Form

FTR #244 HSE

A. BASIC DATA

(Trigon staff shall complete this field trip report within 48 hours after returning from the field and ensure that it is sent properly distributed within 72 hours after leaving the construction site)

Program (JSEP or SKEP): SKEPPHASE: IIIPACKAGE: 2School Name: Thahr Al Sarow Basic Shool For BoysSupervisory Engineer (SE) Name: Wahib Medanat Consultant Engineers (Medanat)Construction Contractor (CC) Name: Dijlah Construction Contracting Est.Date and Time of Field Trip: January 6, 2021 10:30 AMDate of Report: January 11, 2021Weather During Visit: SunnyReport Submitted By: Trigon's HSE Engineer, Odai Tawalbeh

PURPOSE OF VISIT

General Site Inspection (Quality) <u>Corrective Action (CA) Review Report</u> <u>Heath, Safety & Environment (HSE)</u> Site Meeting Substantial Completion Inspection Handover (First Inspection) Second Final Inspection OTHER (list below)

PERSONNEL ON TRIP

No.	Name	Title	Agency		
1	Odai Tawalbeh	HSE Engineer	Trigon Jordan (CMTO)		
2	Abedalaziz Abu Wandi	Civil Engineer	Trigon Jordan (CMTO)		

PERSONNEL AT SITE (if a site meeting or a final inspection, use attachment to list other participants)

No.	Name	Name Title					
1	Mohanned Abu Rshaid	GM	Dijlah Contracting				
2	Natheer Amareen	PM	Wahib Medanat				
3	Alaa Olaimat	SE	Wahib Medanat				
4	Moh'd Mbaydeen	Safety Officer / P2	Wahib Medanat				
5	Amer Abedalghani	PM / P2	Dijlah Contracting				
6	Abedalmalek Al-Husban	SE	Dijlah Contracting				
7	Muheeb Al-Wahidi	Safety Manager / P2	Dijlah Contracting				
8	Ahmad Abedalhadi	Safety Officer	Dijlah Contracting				
9	Adnan Jameel	Tech. Foreman	Dijlah Contracting				



B. QUALITY, SCHEDULE AND H&S FINDINGS CHECKLIST

(For any "No" answer in this section, the Observer shall provide a narrative explanation in Section C. of this Report including corrective action requested) <u>NA-Not Applicable, DC-Didn't Check</u>

		Construction Contractor	Supervisory Engineer
A. SITE DO	CUMENTATION		
1.	Drawings and Specifications on site? (Y/N)		
2.	CC HSE Plan on site? (Y/N)	Y	Y
3.	CC QC Plan on site? (Y/N)		
4.	As-Built Drawings up to date? (Y/N)		
5.	Hard copy files neat and up to date? (Y/N)		
6.	Inspector's Daily Journal up to date? (Y/N)		

B. SCHEDULE

- 7. SE has up to date CC Schedule on site? (Y/N)
- 8. CC has up to date CC Schedule on site? (Y/N)

C. EXIT OBSERVATIONS

- 9. What time does CC start work each morning on average?
- 10. What time does CC stop work each day on average?
- 11. What is the average # of hours worked each day?

C. DESCRIPTION OF FINDINGS

(State if fact or opinion. Use attachments, maps, sketches if necessary)

A. SITE DOCUMENTATION

B. HEALTH, SAFETY & ENVIRONMENT

- 1. <u>For more information about HSE status at the site, please see the attached</u> <u>Trigon HSE Field Trip Report later in this form.</u>
- 2. For more information about Contractor's compliance with the COVID-19 <u>MOL Measures, please see the attached JSEP and SKEP H&S Activities</u> <u>According to the Ministry of Labor (MOL) Working Procedures for Safety</u> <u>(Construction Projects) later in this form.</u>

C. GENERAL QUALITY OBSERVATIONS

D. SCHEDULE



- E. STATUS OF UTILITY CONNECTIONS / OTHER OUSTANDING ISSUE
 - 1. Water Supply:
 - 2. Wastewater:
 - 3. Electricty:
 - 4. Other Issue:

ATTACHMENTS – as marked below

- 1. QUALITY CHECKLIST
- 2. MEETINGS / INSPECTION MINUTES
- 3. HEALTH, SAFETY & ENVIRONMENT ATTACHMENT



E. PHOTOS



Figure #1: Project ID Sign Board on site. Photo credit: Odai Tawalbeh. 1/6/2021





Figure #2: Excavation not properly protected against collapse – immediate action required. Photo credit: Odai Tawalbeh. 1/6/2021



Figure #2 – CORRECTIVE ACTION PLAN CLOSED. Photo credit: Odai Tawalbeh, 1/6/2021



Figure #3: Utility poles that were observed within site boundaries – this item must be addressed by the responsible party. Photo credit: Odai Tawalbeh, 1/6/2021



Figure #4: Unsafe scaffolding and platform units that were observed on site – must be properly erected and secured. Photo credit: Odai Tawalbeh, 1/6/2021

n		-	-				
P	ort	Atta	achment				
1/0	6/202	21 10:3	0				
_				For Boy	ys		
Jer	rash						
SK	(EP /	PH III /	/ P 2				
			-	i Tawal	beh		
-		N/A				GENERAL COMMENTS	
-		<u> </u>					
_							
_							
_							
S							
S							
S							
S							
S							
S							
S							
S							
S							
S							
S							
				N	I/A = NOT APPLIACABLE		
	Obs	erv.	Date	SC	Findings	Recommendations	
Y	N	N/A					
	Ν		/ 8/2020	7			
				7 7	The Contractor office trailers were fixed on the test	We highly recomment the Contractor's	
Y	Ν		11/18/2020	7 7	The Contractor office trailers were fixed on the top. edge of an excavation area close to the site entrance. The sides of excavation were supported by temporary. railing system, however, there is still a potential risk of collapse and we are not sure about the bearing strength of the soil.	We highly recomment the Contractor's is make sure that the area noted on this in completely closed to prevent anyone from before doing the soil test and acheiving controls. We also advise the assigned Controls. We also advise the assigned Controls and reducing hazards as controlling risk and reducing hazards key obligations of Contractor in the work Eliminating the risk completely by remo Contractor's office trailers away from the area is the best control possible, because hazard 'does not exist' anymore and car harm. If this is not possible, Substitution best 'option', etc., according to the soil is Approved National Companies for Labo Soil, lists presumed bearing strengths for of soils. Very fine soils (clays and silts) ty lower capacities than coarse granular so gravels) so, the type and density of the r also important.	
Y	Ν		11/18/2020		edge of an excavation area close to the site entrance. The sides of excavation were supported by temporary railing system, however, there is still a potential risk of collapse and we are not sure about the bearing strength	make sure that the area noted on this in completely closed to prevent anyone fro before doing the soil test and acheiving controls. We also advise the assigned Co aware of and cognisant of the hierarchy as controlling risk and reducing hazards key obligations of Contractor in the wor Eliminating the risk completely by remo Contractor's office trailers away from the area is the best control possible, because hazard 'does not exist' anymore and car harm. If this is not possible, Substitution best 'option', etc., according to the soil of Approved National Companies for Labo Soil, lists presumed bearing strengths for of soils. Very fine soils (clays and silts) ty lower capacities than coarse granular so gravels) so, the type and density of the r	
	TI Je Sk Sk	Thatra Jerash SKEP/ SKE SK S	Thalf Al Saro Jerash SKEP/PHIII/ SK S V <tr< td=""><td>Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Oda S U N/A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U U S U U S U U I</td><td>Thahr AI Sarow Basic Shool For Boy JerashSKEP / PH III / P 2Trigon's HSE Engineer, Odai TawalSUN/ASSISISUN/ASISISISISISISISISISISISISISISISISISIIISIIIIIIIIIIIIIIIIII<th colspa<="" td=""><td>Thahr Al Sarow Basic Shool For Boys Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Odai Tawalbeh S U N/A S U</td></th></td></tr<>	Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Oda S U N/A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U A S U U S U U S U U I	Thahr AI Sarow Basic Shool For Boy JerashSKEP / PH III / P 2Trigon's HSE Engineer, Odai TawalSUN/ASSISISUN/ASISISISISISISISISISISISISISISISISISIIISIIIIIIIIIIIIIIIIII <th colspa<="" td=""><td>Thahr Al Sarow Basic Shool For Boys Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Odai Tawalbeh S U N/A S U</td></th>	<td>Thahr Al Sarow Basic Shool For Boys Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Odai Tawalbeh S U N/A S U</td>	Thahr Al Sarow Basic Shool For Boys Jerash SKEP / PH III / P 2 Trigon's HSE Engineer, Odai Tawalbeh S U N/A S U



U = UNSATISF	ACT	FORY			
U = UNSATISF		CA,	Date	sc	Current Status
U = UNSATISF	Fo	CA, ollow-up	Date	sc	Current Status
U = UNSATISF	Fo Y	CA,			Current Status
U = UNSATISF	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
	Fo Y	CA, ollow-up			Current Status
management to	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering ontractor to be	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace.	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the	Fo Y Y	CA, ollow-up	1/6/2021	7	Current Status
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the his dangerous	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7	
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the his dangerous se then the	Fo Y Y	CA, ollow-up	1/6/2021	7	CLOSED
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the this dangerous se then the n not cause any	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the this dangerous se then the n not cause any n is the second	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the his dangerous se then the n not cause any n is the second test result. The	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the shis dangerous se then the n not cause any n is the second test result. The oratories and	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the this dangerous se then the n not cause any n is the second test result. The oratories and or different types	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the set then the n not cause any n is the second test result. The oratories and or different types ypically have	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the this dangerous se then the n not cause any n is the second test result. The oratories and or different types ypically have oils (sands and	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the this dangerous se then the n not cause any n is the second test result. The oratories and or different types ypically have oils (sands and	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
U = UNSATISFA management to nspection has om entering it engineering ontractor to be y of risk control s is one of the orkplace. oving the chis dangerous se then the in not cause any n is the second test result. The oratories and or different types ypically have oils (sands and native soil is	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the this dangerous se then the n not cause any n is the second test result. The oratories and or different types ypically have oils (sands and	Fo Y Y	CA, IIIO₩-UP N N/A IIII	1/6/2021 1/6/2021	7 7	
management to nspection has om entering it engineering ontractor to be y of risk control is one of the orkplace. oving the this dangerous se then the n not cause any n is the second test result. The oratories and or different types ypically have oils (sands and	Fo Y Y	CA, ollow-up	1/6/2021 1/6/2021	7 7	

Electrical		N		11/18/2020	7			N	1/6/2021	3	ONGOING
Working At Height		1	N/A	11/18/2020				N/A	1/6/2021		
Lifting Ops.		1	N/A	11/18/2020				N/A	1/6/2021		
Hand Tools, Powered Tools, Heavy		N		11/18/2020	7				1/6/2021	7	
Powered Equip.				11/10/2020			'		1/0/2021	· /	
Public Protection		N		11/18/2020	7			N	1/6/2021	3	OPEN
Concrete R/F Starter Bar		1	N/A	11/18/2020				N	1/6/2021	3	OPEN
Occupational Health		N		11/18/2020	7		Y		1/6/2021	7	
Fire Prevention		N		11/18/2020	7		Y		1/6/2021	7	
Housekeeping Standards		N		11/18/2020	7		Y		1/6/2021	7	
Materials Storage		N		11/18/2020	7		Y		1/6/2021	7	
Welfare Facilities		N		11/18/2020	7		Y		1/6/2021	7	
PPE		N		11/18/2020	7			N	1/6/2021	5	ONGOING
			Т	otal H&S %	<mark>67</mark> %		<u> </u>		Total CA %	58%	
			Ac	tion Status		NEEDS IMPROV.		Ac	tion Status	NE	EDS IMPROV.
Environmental Regulations	ΥI	N N	I/A				Y	N N/A			
Waste Management		N		11/18/2020	7		Υ		1/6/2021	7	
Dust Management		N		11/18/2020	7		Υ		1/6/2021	7	
Tracking / Transporting Waste		N		11/18/2020	7		Y		1/6/2021	7	
Runoff Discharge		1	A/۷	11/18/2020				N/A	1/6/2021		
Noise Nuisance		N		11/18/2020	7		Υ		1/6/2021	7	
Air Pollution		N		11/18/2020	7		Υ		1/6/2021	7	
Land Pollution		N		11/18/2020	7		Υ		1/6/2021	7	
Water Pollution		N		11/18/2020	7		Y		1/6/2021	7	
Environmental Impacts		N		11/18/2020	7		Y		1/6/2021	7	
							+				
			Γotal	Environ. %	70%				Total CA %	70%	

Notes:

1. The above HSE scoring express the Contractor's compliance with each task / activity to find out the average of HSE program performance on site.

2. Each task / activity has a score and all scores above are out of 10. (Leave blank if not applicable)

3. The total percentage for both H&S and Environment will be calculated using the following formulas.

• Total H&S % = [(Total SUM of H&S Score) / (Total No. of Applicable H&S Activities x 10)] x 100

• Total Environmental % = [(Total SUM of Environmental Score) / (Total No. of Applicable Environmental Activities x 10)] x 100

4. Examining this HSE scoring, one can draw two conclusions:

• The total percentage of Health and Safety (H&S) decreased from 67% to 58% indicating that the Action Status of H&S is still Needs Improvement. All areas that were noted on this inspection must be corrected and all systems should meet Site Compliance Protocol.

• The Action Status of Environment is still Compliant.

COMPLIANT >= 70%

70% > NEEDS IMPROVEMENT >= 50%

LEGEND							
L	Low Risk	Manage by routine procedure					
м	Medium Risk	Needs Improvements					
н	High Risk	Immediate action require					

Disclaimer: Trigon field trip reports include information and findings based upon those parts of the construction sites we visit. Our visits and our contract scope of work do not include Trigon to carry out first tier Quality Control/Assurance, i.e., reviewing submittals, drawings and specifications, reviewing contract compliance, or in any way carrying out close supervision of the works. Therefore our field-trip reports include cursory quality, health & safety and schedule information and its entry on our reports is intended to provide the reader only with a sense of our general observations of that part of the job site we have visited.



AT RISK < 50%

JSEP and SKEP H&S Activities According to the Ministry of Labor (MOL) Working Procedures for Safety (Construction Projects)

#	Div. #	MOL Safety Measure / Procedure / Non MOL activity in Blue	Y/N	Comments
Α		First A: Job sites		
I	I	The work on the sites should limited to the basic construction works of the project and with minimal manpower;	Y	
2	2	Commitment to apply work procedures for the applicable safety and preventive measures to reduce the spread of the Corona virus, Directory No. 9 for industrial enterprises chapter issued by the Ministry of Labor excludes Chapter Six (housing buildings residence and tenth) (kitchen and catering market);	Y	
3	3	All office work is done remotely using technical means;	Y	
4	4	Site offices are used only by necessity and by a limited number of persons;	Y	
5	5	A daily work program is presented by the contractor explaining the daily work list of the labor that is required to exist (and to a minimum), including the places of residence phone numbers and mode of transportation;	Y	
6	6	Publications on prevention and control of the spread of the Coronavirus are distributed in all project facilities;	Y	
7	7	Personal Protective Equipment (PPE) is secured for all on site structural by risk type;	Y	
8	8	Adequate disinfection stations are secured in the workplace at the entrances and exits;	Y	
9	9	Work sites and facilities designated for employment are cleaned on a daily basis the contractor using sterile materials;	Y	
10	10	Do not hold any meetings inside the offices and only meet with through technical means of communication.	Y	
		Second: Protection of site workers:		
		Provide all safety and health protection equipment provided that it be limited the minimum is as follows:		
11	I	Provide special clothes to work on the site and prevent them from leaving the site;	Y	
12	2	Providing disposable gloves that are delivered to workers before entering the site and disposing of them before leaving the site and in safe places;	Y	
13	3	Providing a medical mask to prevent the spread of the spray (N95);	Y	
14	4	Establish preventive measures to reduce the spread of fires;	Y	

#	Div. #	MOL Safety Measure / Procedure / Non MOL activity in Blue	Y/N	Comments
15	5	Work to check the temperature of workers at the site before entering the sites and during work and before exiting the site;	Y	
16	6	Adherence to the instructions for spacing between people on the job site and supervisors a minimum of a meter and a half;	Y	
17	7	Preventing gatherings of workers for whatever reasons;	Y	
18	8	Providing individual meals to limit gatherings;	Y	
19	9	The Occupational Safety and Health Supervisor follows up on all instruction prevention of the outbreak of new COVID- 19 virus and the procedures outlined above;	Y	
20	10	The contractor is obliged to secure the required quarantine to the sites approved by the authorities competent;	Y	
21	11	Continue to change medical masks every two hours for exposed workers to dust directly;	Y	
22	12	Providing quantities of water for workers distributed in each work site and easy access to it;	Y	
23	13	The setting of mandatory signs prevents touching the face and adherence to special equipment safety and according to the construction standards and equipment for the viral risks such as medical masks and medical gloves before wearing business gloves structural;	Y	
24	14	Commitment to occupational safety and health standards, instructions and regulations issued under the Jordanian Labor Law;	Y	
25	15	Commitment by contractors to implement system No. (7) and system No. (42) and regulation (43) according to the requirements of the Labor Law;	Y	
26	16	Do not use long-term (washable) masks for construction workers exposed to dust.	Y	
		Third: Mobility		
27	I	Transfer (workers and supervisors) according to Guide No. (11), the means of transportation issued by Ministry of Labor.	Y	
28	2	The vehicles used by the contractor to transport the workers are determined. (Assume this to mean disinfected)	Y	
		Fourth AA: Cargo transportation		
29	I	All incoming and outgoing vehicles are disinfected by spraying materials disinfection and isolation of the driver directly in the disinfection area located in entrances and exits of the project;	Y	

#	Div. #	MOL Safety Measure / Procedure / Non MOL activity in Blue	Y/N	Comments
30	2	All Flyer awareness flyers for COVID-19 are distributed to all drivers;	Y	
31	3	Providing all drivers with personal protective equipment through a box dedicated for this equipment.	Y	