

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Jumana Bint Abi Taleb Basic Mixed - Marka**
Package **Package 2**
Contractor **Dijlah Est. Construction Co.**
Tender No. **10/2019/USAID/SKEP/3/2**

Rep No. **QC-23 14**
Date **15 / 01 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Defected stones at facades. 2. Cumulating debris in contact with stone walls.	1. Replacing. 2. To be removed outside the site.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
The Contractor responded immediately to rectify the remarks.		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Defected stones and cumulative debris

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

2/3

2/1/2022

Quality Control Report

Photos After:



Replacing defected stones and removal of debris

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature