

# Quality Control Report

**Consultant** **Wahib Medanat** Consultant Engineers  
**Site Name** **Um Al Dananir Basic Mixed - Balqa**  
**Package** **Package 1**  
**Contractor** **Derar Saraireh & Sons for Engineering & Contracting**  
**Tender No.** **1/2020/USAID/SKEP/3/1**

**Rep No.** **QC-11 02**  
**Date** **8 / 02 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Minor and limited segregation in the boundary wall as shown in the attached photo.	Repair using approved materials	Contractor, immediately.
<b>Report Prepared by</b>	Hassan Shaqbua, Supervision Quality Control Manager	

## Contractor's Response

The Contractor responded positively and promptly and repaired as required.		
<b>Notes</b>		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

# Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

# Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature