

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 04**
Date **27 / 03 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Damaged cartonal protecting the insulation of the walls under slab on grade.	Replace the damaged cartonal by new cartonal boards and re-fix properly	Immediately by Contractor

Report Prepared by

Hassan Shaqbua, Supervision
Quality Control Manager

Contractor's Response

the contractor responded positively and promptly

Notes

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature