

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Khadija Bint Khwailed Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-13 18**
Date **25 / 06 / 2022**

Description of Non Conformance	Corrective Action	Required by / When
1. Built stones at façade need cleaning. 2. Air voids at the waterproofing membrane at the roof. 3. Waving in plastering for walls and ceilings. 4. Black spots at granite cladding.	1. Clean. 2. Replace. 3. Rectify 4. Replace.	The Contractor/Immediately
Report Prepared by	Hassan Shaqbua, Supervision Quality Control Manager	
Contractor's Response		
Notes		

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report

Before Photos:



Stone facades need cleaning



Air voids at the waterproofing membrane

Consultant Site Engineer

Signature


Contractor Site Engineer

Signature

Quality Control Report



Waving in plastering at walls



Waving in plastering at ceilings


Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report



Black spots in granite coping

Consultant Site Engineer

Signature

Contractor Site Engineer

Signature

Quality Control Report

Photos After:



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature