

Quality Control Report

Consultant **Wahib Medanat** Consultant Engineers
Site Name **Um Al Dananir Basic Mixed - Balqa**
Package **Package 1**
Contractor **Derar Saraireh & Sons for Engineering & Contracting**
Tender No. **1/2020/USAID/SKEP/3/1**

Rep No. **QC-11 03**
Date **15 / 03 / 2021**

Description of Non Conformance	Corrective Action	Required by / When
Segregation and roughness in column neck no. (7) and (1)- axis J/7- K/7	Demolition of defected areas and re-cast in accordance to approved method statement	Immediately by Contractor

Report Prepared by

Hassan Shaqbua, Supervision
Quality Control Manager

Contractor's Response

Site memo was issued to the Contractor and his action is awaited		
--	--	--

Notes

--	--	--

Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Contractor Site Engineer

Signature

Signature

Quality Control Report



Consultant Site Engineer

Signature

Contractor Site Engineer

Signature