



## SKEP III Home Office Support Site Visit Report



Consultant	Wahib Medanat Consultant Engineer	Rep No.	23-29062021
Contractor	Dijlah Establishment Constr. Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Jumana Bint Abit Taleb Basic Mixed School - Jerash	Day/ Date	Tus. 29/06/2021
Duration of Project	450 Calendar Days	Total Project Budget	8,314,983.735 JD

No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Wahib Medanat	-Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	-Head of Mechanical Department	
5	Hasan Shaqboua	-Quality Control Manager	

## Visit Notes

No.	Description
1	During the site visit
	A Request that for the purposes of first fix installation, the block should be saw cut. Medanat SE confirmed that the block is already saw cut, but the seen view was due to plastering work-2 <sup>nd</sup> layer over the electrical first fix pipes.
2	Medanat SE confirmed that he requested the Contractor several times to provide a special mortar mixing container with reasonable size to keep the water content in the mix and to avoid accumulation of residues of mixes. Currently three containers are available and under use in the site.



USAID FROM THE AMERICAN PEOPLE





No.	Description
3	The relationship between the electric shutter door and the blockwork walls was discussed including the way that the door shall be installed.
4	The visitors reminded the Contractor's staff to spray water at the entrance of the site for the purpose of dust control. The Contractor was immediately directed and he did as requested.









Project ID Sign on Site









Temperature check, sterilization and signing visitors' attendance sheet at the entrance of the site, complying with Covid-19 Protocol

























Formwork for external walls behind stone



Eng. Hasan/Quality Control Manager explaining how the second layer of plastering shall be executed










Observing work quality



Eng. Yousef/Medanat Site Engineer gave a brief about the building area, number of floors and facilities







Formwork for door jambs and lintels



Formwork for lintels of internal windows

8,368\Hor

\\SERVER\Data\E\PROJECTS FILES\368\Home office support Site Visits\June Visits\23-29062021.docx

Form # QP SUP 01-18, Rev.1










Medanat SE confirmed that he requested the Contractor several times to provide special mortar mixing container with reasonable size to keep the water content in the mix and to avoid accumulation of residues of mixes. Currently three containers are available and under use in the site













A tour around the project