



Consultant	Wahib Medanat Consultant Engineer	Rep No.	23-16082022
Contractor	Dijlah Establishment Constr. Contracting	Tender No.	(11/2019/USAID/SKEP/3/S) Schools for a Knowledge Economy Project (SKEP) - Phase (3) Package (1, 2)
Site Name	Jumana Bint Abit Taleb Basic Mixed School - Jerash	Day/ Date	Tue. 16/08/2022
Duration of Project	450 Calendar Days	Total Project Budget	8,314,983.735 JD

No.	Visitors		Remarks
1	Suhair Amarin	- Project Dir./Head of Architectural Department	
2	Hashem Abu Kwaik	- Senior Civil Engineer	
3	Akram Khammes	- Head of Electrical Department	
4	Marwan Sonna'a	- Head of Mechanical Department	
5	Hasan Shaqboua	- Quality Control Manager	

### Visit Notes

No.	Description
1	The Supervision team discussed the built stone at the facades.
2	The team checked the quality of the installed windows protections screens.
3	The team inspected the painting work for the external steel.
4	The team discussed the rectification work for the painting of the basketball court.
5	The team noted the initiation of Hera design works.



No.	Description
6	The team Inspected granite coping at corridors and found it executed as required.
7	The team observed the installation of the suspended ceiling.
8	The team Marked the last stage of tiling, doors and sanitary fixtures installation .



Project ID  
Sign on Site





General view of the project site

(figures: 01, 02, 03 & 04)

(Figure: 01)



(Figure: 02)



WAHIB  
MEDANAT  
consultant engineers



(Figure: 03)




(Figure: 04)



(Figure: 05)

The Supervision team discussed the built stone at the facades and the quality of the installed windows protection screens

(Figure: 05 & 06)




(Figure: 06)



Inspecting rectification work for the painting at the basketball court

(Figure: 07)



The team  
Observed the  
painting of the  
external  
installed steel

(Figure: 08)





The team noted the initiation of Hera design works

(Figure: 09)



The team found the granite coping at the corridors executed as required

(Figure: 10)



(Figure: 11)

Marking the last stage of tiling, doors and sanitary fixtures installation



(Figure: 11 & 12)

(Figure: 12)



The team inspected the installation of the suspended ceiling and other works at the multi-purpose hall

(Figure: 13)